# AWNING WINDOW INSTALLATION PROCEDURE

Installation tools and accessories.



a.Hexagonal tool



b.Electric drill



h.Laser level meter



c.Fixed installation screw



d.installation expansion screw



e.Rubber plug





f.Handle




F.fixed handle screw


### Horizontal measurement






### Frame installation







## Outer frame length 71.02in



Outer frame height 45.70in



Outer frame width
4.01in




profile thickness
0.78in

#### F.fixed handle



f.handle





Punch holes on the left and right sides.

c.Fixed installation of screw extension of the screw extension of th

d.installation expansion screw